

VOLVO L60E

Description

Volvo L60E, Engine and model Volvo D6D LCE2, 90 kW, EPA, Air conditioning, Erops cabin, 20.5R25, GP bucket with bolt on edge, Width of the bucket 2.50m, Complete steering wheel, Autoshift, Backup alarm, Weight load indicator available but not tested, Beacon, In good and clean condition.



Year	2004
Hours	16746
Weight	13.000 kg
Serial number	L60EV1374
Reference	208857



[Download photos](#)

CONTACT US:
SALES@SMITMA.COM
+31(0)773999840

New/Excellent ★★★★★	Very good ★★★★☆	Good ★★★☆☆	Fair ★★★☆☆	Poor ★★☆☆☆
------------------------	--------------------	---------------	---------------	---------------



INSPECTION REPORT

FEATURES

Engine and model	Volvo D6D LCE2
Engine power	90 kW
EPA	EPA
Erops cabin	✓
Tyre size	20.5R25
Bucket	GP bucket with bolt on edge
Width of the bucket	2.50m
Steering	Complete steering wheel
Autoshift	✓
Beacon	✓
Overall condition	In good and clean condition.

DOCUMENTS

Parts book	✓
Operation manual	✓

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★ ★ ★ ★ ★
Decals	★ ★ ★ ★ ★
Bonnet	★ ★ ★ ★ ★
Chassis	★ ★ ★ ★ ★
Steps/ladders	★ ★ ★ ★ ★
Grab irons	★ ★ ★ ★ ★
Cabin	★ ★ ★ ★ ★
Pre-cleaner bowl	★ ★ ★ ★ ★

ENGINE DETAILS AND CONDITION

Engine number	00871838
EPA sticker available	Yes
Air cleaner	Clean
Anti-freeze level °C	-21°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes

Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★☆
Muffler	★★★☆☆
Exhaust stack	★★★★☆
Engine supports	★★★★☆
Hoses	★★★★☆
Good cold start	Yes
Engine power	★★★★☆
Blow by	★★★★☆
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★☆
Fan	★★★★☆
Radiator	★★★★☆

OPERATOR STATION

Hourmeter	Working
Air conditioning	Not working
Heater	Working
Gauges	Few don't work
Switches	★★★★☆
Display	★★★★☆
Warning	No warnings available
Mirrors	Not broken
Cabin glass	Not broken
Windshield wipers	Working
Interior lights	Not working
Cabin floor	★★★★☆
Interior roof	★★★★☆
Seat	★★★☆☆
Door lock	Not working

BUCKET

Overall condition of the bucket	★★★★☆
---------------------------------	-------

Bottom	★★★★★
Sides	★★★★★
Cutting edge	★★★★★

FRAME

Play articulation point	★★★★★
Play loading frame	★★★★★
Play bucket pins	★★★★★
Crack or welds	No

HYDRAULICS

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Hydraulic valves leaking	No
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★★

BRAKE

Service brake operation	★★★★★
Parking brake operation	★★★★★
Compressor	★★★★★

DRIVE TRAIN/TRANSMISSION

Transmission fully operational in all gears forward and reverse	Yes
Transmission oil level ok	Yes
Transmission noisy	No
Oil level front axle ok	Yes
Oil level rear axle ok	Yes

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★★
Batteries	★★★★★
Starter	★★★★★
Cabin lights working	Yes
Tail lights working	Yes
Additional work lights working	Yes

SAFETY ITEMS

Backup alarm	Working
Seat belt	Available
Horn	Working
Beacon	Working

TYRES

FRONT LEFT

Tread dept in mm 22mm

REAR LEFT

Tread dept in mm 6mm

REAR RIGHT

Tread dept in mm 10mm

FRONT RIGHT

Tread dept in mm 12mm

New/Excellent



Very good



Good



Fair



Poor

