

VOLVO L90F

Description

Volvo L90F, Engine and model Volvo D6E LAE3, 128 kW, EPA, CE, Air conditioning, Erops cabin, 20.5R25 Michelin , Hydraulic quick release, GP bucket with welded edge, Width of the bucket 2.88m, 3rd valve, Complete steering wheel, Autoshift, Backup camera, Backup alarm, Weight load indicator available but not tested, Cental lubrication available but not tested, Beacon, AM/ FM radio, In very good and clean condition.



Year	2011
Hours	15749
Weight	17.100 kg
Serial number	VCE0L90FT00028024
Reference	208583



[Download photos](#)

CONTACT US:
SALES@SMITMA.COM
+31(0)773999840

New/Excellent



Very good



Good



Fair



Poor



INSPECTION REPORT

FEATURES

Engine and model	Volvo D6E LAE3
Engine power	128 kW
EPA	EPA
CE	✓
Erops cabin	✓
Tyre size	20.5R25 Michelin
Bucket	GP bucket with welded edge
Width of the bucket	2.88m
Steering	Complete steering wheel
Autoshift	✓
Central lubrication	Cental lubrication available but not tested
Beacon	✓
Overall condition	In very good and clean condition.

DOCUMENTS

Parts book	✓
Operation manual	✓

GENERAL APPEARANCE

Stamped serial number checked	Yes
Serial number plate checked	Yes
Paint	★★★★☆
Decals	★★★★☆
Bonnet	★★★★☆
Engine cover doors	★★★★☆
Chassis	★★★★☆
Steps/ladders	★★★★☆
Grab irons	★★★★☆
Cabin	★★★★☆
Pre-cleaner bowl	★★★★☆

ENGINE DETAILS AND CONDITION

Engine number	11478259
EPA sticker available	Yes
Air cleaner	Clean

Anti-freeze level °C	-38°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★★
Muffler	★★★★★
Exhaust stack	★★★★★
Engine supports	★★★★★
Hoses	★★★★★
Good cold start	Yes
Engine power	★★★★★
Blow by	★★★★★
Knocking	No
Compression in the radiator	No
Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★★
Fan	★★★★★
Radiator	★★★★★

OPERATOR STATION

Hourmeter	Working
Air conditioning	Working
Heater	Working
Gauges	Working
Switches	★★★★★
Display	★★★★★
Warning	No warnings available
Mirrors	Not broken
Cabin glass	Not broken
Windshield wipers	Working
Interior lights	Working
Cabin floor	★★★★★
Interior roof	★★★★★
Seat	★★★★★
Door lock	Working

BUCKET

Overall condition of the bucket	★★★★★
Bottom	★★★★★
Sides	★★★★★
Cutting edge	★★★★★

FRAME

Play articulation point	★★★★★
Play loading frame	★★★★★
Play bucket pins	★★★★★
Crack or welds	No

HYDRAULICS

Hydraulic oil level ok	Yes
Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Hydraulic valves leaking	No
Noise hydraulic pump normal	Yes
Operating condition hydraulics	★★★★★

BRAKE

Service brake operation	★★★★★
Parking brake operation	★★★★★
Compressor	★★★★★

DRIVE TRAIN/TRANSMISSION

Transmission fully operational in all gears forward and reverse	Yes
Transmission oil level ok	Yes
Transmission noisy	No
Oil level front axle ok	Yes
Oil level rear axle ok	Yes

ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★★
Batteries	★★★★★
Starter	★★★★★
Cabin lights working	Few lights don't work

Tail lights working	Few lights don't work
Additional work lights working	Yes

SAFETY ITEMS

Backup alarm	Not working
Seat belt	Available
Horn	Working
Beacon	Working

TYRES

FRONT LEFT

Tread dept in mm	38mm
Percentage life remaining	50%

REAR LEFT

Tread dept in mm	34mm
Percentage life remaining	40%

REAR RIGHT

Tread dept in mm	38mm
Percentage life remaining	50%

FRONT RIGHT

Tread dept in mm	16mm
Percentage life remaining	20%

New/Excellent



Very good



Good



Fair



Poor



Copyright Smitma BV

